


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-029	Smoke	8/18/2008	ADS/TM	S11YY_008MH	Dry	Yes	1,307.15



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-029	Smoke	8/18/2008	ADS/TM	S11YY_008MH	Dry	Yes	1,307.15

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11YY_003G1	S11YY_003MH	S11YY_008MH	229.5790	8
S11YY_004G1	S11YY_004MH	S11YY_006MH	179.0406	8
S11YY_017G1	S11YY_017MH	S11YY_004MH	319.2986	8
S11YY_008G1	S11YY_008MH	S11YY_018MH	299.4235	8
S11YY_018G1	S11YY_018MH	S11YY_017MH	279.8070	8

Observations & Photos

Obs_ID S1028-029-OB01

Address 3313 Sequoia Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11YY_008MH

Comments Smoke from cleanout in back yard access through alley way. 3313 Sequoia Ave.



Picture \S1028-029-OB01-P01.jpg

Comments Back of house, 3313 Sequoia Ave.

